


FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst. Engineer)

(Re: G.O. Ms. 20/70/ PWD Dt. 23 - 01 -1970)



1. Name of the Officer

2. Name of the School

ST. MARY'S RESIDENTIAL CENTRAL SCHOOL

3. Location with name of Education/District/Sub-Districts

TRIVANDRUM

4. Classification of Building as specified in column 4 of the application for fitness certificate and size.

Building I : R.C.C Four storied building (14.40mht) ✓

Ground Floor : (1) 22.37m x 6.43 + Varandha-1.7m ✓

(2) 12.46m x 6.2m → passage-1.83m ✓

(3) 2.63m x 7.71 m – Store, Toilet etc ✓

(4) 5.73m x 6.51m + passage- 1.53m ✓

(5) 7.23m x 3.03m- stair ✓

(6) 7.07m x 1.53m- stair ✓

First Floor : (1) 22.37mx 6.43m ✓

(2) 12.46m x 6.2m + passage – 1.83 m ✓

(3) 2.63m x 7.71 Utility room, toilet etc ✓

(4) 5.73m x 6.51m + passage- 1.53m ✓

Second Floor : (1) 22.37m x 8.13- Lab ✓

(2) (12.46m x 6.20 m) + (9.75m + 1.83m) – lab ✓

(3) 2.63m x 7.71 m – Store, Toilet etc ✓

(4) 5.73m x 6.51m + passage- 1.53m ✓

Third Floor : (1) 22.37m x 8.13- Lab ✓

(2) (12.46m x 6.20 m) + (9.75m + 1.83m) – lab ✓

(3) 2.63m x 7.71 m – Store, Toilet etc ✓

(4) 5.73m x 6.51m + passage- 1.53m ✓

Building II : Single storied sheet Roofed Building (6.40 m ht) ✓

(1) 20.48m x 9.70 m ✓

(2) 11.47m x 5.15m ✓

- (3) 9.20m x 6.58m ✓
- (4) 6.81m x 18.83 m ✓
- (5) 3.06m x 6.15m ✓
- (6) 3.06m x 1.66m ✓
- (7) 53.84 m x 8.93m ✓
- (8) 18.87m x 6.20m ✓
- (9) 6.50m x 3.83m ✓
- (10) 8.25m x 18.70m ✓
- (11) 18.80m x 8.20m ✓
- (12) 4.60m x 7.43m ✓
- (13) 7.75m x 20.59m ✓
- (14) 38.80m x 8.09m ✓
- (15) 18.90m x 6.25m ✓
- (16) 6.50m x 3.83m ✓
- (17) 1.50m x 3.02m ✓
- (18) 29.11m x 8.18m ✓
- (19) 9.53m x 6.22m ✓
- (20) 8.16m x 6.23m ✓

5. Period for which the certificate is issued: 2019 - 2020

6. Nature of defects, if any

- a) Foundation & basements Nil
- b) Super structure Nil
- c) Doors & windows Nil
- d) Woodwork wrought and putup Nil
- e) Roof Nil
- f) Flooring Nil

FITNESS CERTIFICATE

g) Miscellaneous (cracks etc) _____

Nil

7. Any major defects noticed which will render _____

Nil

the building unsafe in any manner

8) Whether maintenance work have been done properly _____

yes

Whether the structure is sound or not for conducting classes

The buildings are sound under normal weather conditions.

verified by SPMS

Note : 1. The stability of the structure should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate

CERTIFICATE

certified that the school building was inspected by me on 25/03/2019 and

found to be fit / unfit to conduct classes, for the period of one year for the

reasons stated above.

Place

TRIVANDRUM

Date

25/3/2019

(Seal)

7993-6-13

[Handwritten Signature]

Assistant Engineer

25/3/2019

[Handwritten initials]



For St. Mary's Residential Central School

[Handwritten Signature]
Secretary

[Handwritten Signature]

PRINCIPAL
ST. MARY'S RESIDENTIAL CENTRAL SCHOOL
POOJAPPURA, TRIVANDRUM